

Additive Manufacturing Technology and Trends

MCA Session Topic: CAD to CAM





6/26/22

Instructors:

1. Alex Raymond Renner: arenner@iastate.edu
2. Michael Holm: mdholm@iastate.edu


Session 1 In-Class Activity Discussion

- Open the mug or donut in PrusaSlicer or Cura (if you haven't already done so)
- Did we get the same result in all software applications?
- Why does the missing face cause issues?



Eight Steps¹ in Additive Manufacturing

1. Conceptualization and CAD
2. Conversion to STL/AMF
3. Transfer to AM Machine and STL File Manipulation
4. Machine Setup
5. Build
6. Removal and Cleanup
7. Post-Processing
8. Application




- The **rapid** part of the process
- Users **assume** Additive Manufacturing is the **best** solution.
- Expenses and potential cost savings are **high**.

Transition from CAD to Machine

- Often involves two people, causing potential issues:
 - Designer's intent may conflict with Additive Manufacturing (AM) requirements
 - AM Machine operator often does not know designer intent
- “AM language” barriers
 - Lack of verbal communication between two people quality is not a function of quantity
 - Digital data elements, transfer method(s), and unique accept/reject criteria

CAD to CAM

- Iterative Process
- Consult 3D printer operator as early as possible
- Not just designing to meet customer requirements
 - Non-manifold geometry
 - 3D Printer considerations (how good can the machine make it)
 -




Designer to AM User Discussion

Designer	AM User
“Is my STL ok?”	“I’m sure your design is great!”
“No, I mean is it going to print?”	“That’s hard to say”
“WHAT! I was told you were the expert?”	“Well I have lots of experience, just not with your design.”
“AHAH, so you DON’T like my design, I knew it!!!”	“[mumbling] apparently I need a PhD in Engineering and be a magician”

MCA Session 1 Activity Review

- Good converters use BREP surface connections when converting to STL.
- Once exported to STL can you go back to “perfect CAD”?
- Michael: “explain why STL to CAD is not possible in a blog post - and you’ll be asked to help on doing the impossible conversion anyway”.



CAD Export Options

- STL/AMF



- Mesh 3D model format ISO/ASTM 52900

- What's do they have in common?

- Export Resolution = CAD Approximation Tolerance



- Chordal Deviation?

- Angle Tolerance?




Tessellation

- OBJ, VRML, STL?
- Engineering CAD Settings
- Exporting an approximation
 - Coarse or Fine?
 - Binary or ASCII?
 - Chordal Deviation?
 - Angle Tolerance?



*What is the error for a prismatic part?

Approximation Error



188 facets

728 facets

4,232 facets



35,804 facets

← Error

File size (#of facets) →

Trade off of error versus file size (number of facets)

Chordal Deviation and Angle Tolerance



STL vs. STL 2.0 (AMF)

- ◉ Additive Manufacturing Format (AMF) has been called STL 2.0
- ◉ May contain additional information such as color, volume, units that some AM machines need
- ◉ Fundamental concepts of the STL format are incorporated
- ◉ Still under development, could but does not need to replace the STL format

```
<?xml version="1.0" encoding="UTF-8"?>
<amf unit="millimeter" version="1.1" xml:lang="en"><constellation id="0">
  <instance objectid="2922"/></constellation><object id="2922" type="model">
    <mesh>
      <vertices>
        <vertex><coordinates><x>-12.7</x><y>-12.7</y><z>-12.7</z></coordinates></vertex>
        <vertex><coordinates><x>12.7</x><y>-12.7</y><z>-12.7</z></coordinates></vertex>
        <vertex><coordinates><x>-12.7</x><y>-12.7</y><z>12.7</z></coordinates></vertex>
        <vertex><coordinates><x>12.7</x><y>-12.7</y><z>12.7</z></coordinates></vertex>
        <vertex><coordinates><x>-12.7</x><y>12.7</y><z>-12.7</z></coordinates></vertex>
        <vertex><coordinates><x>12.7</x><y>12.7</y><z>-12.7</z></coordinates></vertex>
        <vertex><coordinates><x>-12.7</x><y>12.7</y><z>12.7</z></coordinates></vertex>
        <vertex><coordinates><x>12.7</x><y>12.7</y><z>12.7</z></coordinates></vertex>
      </vertices>
      <volume>
        <triangle><v1>2</v1><v2>6</v2><v3>0</v3></triangle>
        <triangle><v1>6</v1><v2>4</v2><v3>0</v3></triangle>
        <triangle><v1>1</v1><v2>2</v2><v3>0</v3></triangle>
        <triangle><v1>4</v1><v2>1</v2><v3>0</v3></triangle>
        <triangle><v1>5</v1><v2>3</v2><v3>1</v3></triangle>
        <triangle><v1>3</v1><v2>2</v2><v3>1</v3></triangle>
        <triangle><v1>4</v1><v2>5</v2><v3>1</v3></triangle>
        <triangle><v1>7</v1><v2>6</v2><v3>2</v3></triangle>
        <triangle><v1>3</v1><v2>7</v2><v3>2</v3></triangle>
        <triangle><v1>5</v1><v2>7</v2><v3>3</v3></triangle>
        <triangle><v1>6</v1><v2>7</v2><v3>4</v3></triangle>
        <triangle><v1>7</v1><v2>5</v2><v3>4</v3></triangle>
      </volume>
    </mesh>
  </object>
</amf>
```




```
solid cube
  facet normal 1.000000e+000 1.365924e-016 0.000000e+000
    outer loop
      vertex 1.000000e+000 1.000000e+000 1.000000e+000
      vertex 1.000000e+000 0.000000e+000 1.000000e+000
      vertex 1.000000e+000 1.000000e+000 0.000000e+000
    endloop
  endfacet
  facet normal 1.000000e+000 1.365924e-016 0.000000e+000
    outer loop
      vertex 1.000000e+000 1.000000e+000 0.000000e+000
      vertex 1.000000e+000 0.000000e+000 1.000000e+000
      vertex 1.000000e+000 0.000000e+000 0.000000e+000
    endloop
  endfacet
  facet normal 0.000000e+000 1.000000e+000 0.000000e+000
    outer loop
      vertex 0.000000e+000 1.000000e+000 1.000000e+000
      vertex 1.000000e+000 1.000000e+000 1.000000e+000
      vertex 0.000000e+000 1.000000e+000 0.000000e+000
    endloop
  endfacet
```

STL Files: Made for 3D printing

- De-Facto” standard file for RP
- A faceted representation of the boundary of a part, where each facet is a triangle
- Process of creating this representation is called “Tessellation”
- The STL file is an approximation of the surfaces of the part




MCA Session 2, Activity #1

- Sketch the cylinder and triangular extruder shape
- Sketch hyperrectangle shapes inside the cylinder and extruded triangle shapes



Near-CAD Model Analyses

- Does not open in 3D printer software?
- Does open but does not print “well”?
- Is there an intermediate step?
- If so: what else can you do as the designer...?



Rules Make STL Files Good




● Calculated Normals

- Normals calculated with cross-product
- Normals generated during export and stored with each facet's vertex information


● Vertex to Vertex Rule

- Every triangle must share exactly two vertices with each adjacent triangle.
- Every segment must be shared by two and only two triangles


```
solid BOX3
facet normal 0.000000e+00 0.000000e+00 -1.000000e+00
  outer loop
    vertex 2.000000e+00 0.000000e+00 0.000000e+00
    vertex 0.000000e+00 0.000000e+00 0.000000e+00
    vertex 0.000000e+00 2.000000e+00 0.000000e+00
  endloop
endfacet
```



*The facet normal always points to the "outside"




VALID




INVALID

STL Tessellation Errors


Overlapping
Facets





Missing Facets



Degenerate
Facets




Cannot Slice if not Watertight




10 Minute Break


Slicing an STL File



Intersect With Z-Plane




- Every segment belongs to exactly two triangles (vertex to vertex rule)
- Right hand rule...
- STL facet normals always point to the “outside” of the 3D model
- Now we can find the adjacent facet...
- If segment 3-1 exists, then segment 1-3 must exist, otherwise?




```

solid BOX3
facet normal 0.000000e+00 0.000000e+00 -1.000000e+00
  outer loop
    vertex 2.000000e+00 0.000000e+00 0.000000e+00
    vertex 0.000000e+00 0.000000e+00 0.000000e+00
    vertex 0.000000e+00 2.000000e+00 0.000000e+00
  endloop
endfacet
facet normal -1.000000e+00 0.000000e+00 0.000000e+00
  outer loop
    vertex 0.000000e+00 2.000000e+00 1.000000e+00
    vertex 0.000000e+00 2.000000e+00 0.000000e+00
    vertex 0.000000e+00 0.000000e+00 0.000000e+00
  endloop
endfacet
facet normal 0.000000e+00 0.000000e+00 -1.000000e+00
  outer loop
    vertex 2.000000e+00 2.000000e+00 0.000000e+00
    vertex 2.000000e+00 0.000000e+00 0.000000e+00
    vertex 0.000000e+00 2.000000e+00 0.000000e+00
  endloop
endfacet
...
endsolid BOX3
  
```







If Segment 3-1 exists, then segment 1-3 must also exist...else?





Increment Z height

1. Green plane slices through STL
2. Resulting 2D contour Plotted
3. Change Z position
4. Repeat



Color In-Between The Slice File Lines


- CCW polygonal chains are exterior chains
- CW polygonal chains are interior chains
- Machine fills in using slice file polygon chain
- Fill based on polygon chain CW or CCW calculation
- “Raster” is the term for how filling occurs



What's Up?

- Once you slice, you defined what's up*
 - Must re-slice the 3D model for any and every orientation change
 - Beneficial if you know how orientation changes
- 3D Models can be sliced from any orientation
 - AM user's "Best" orientation depends on slices and layers
 - Designer's "Best" orientation depends on features/aspects of the design


```
J1116 D043
facet normal 0.000000e+00 0.000000e+00 * -1.000000e+00
  outer loop
    vertex 2.000000e+00 0.000000e+00 0.000000e+00
    vertex 0.000000e+00 0.000000e+00 0.000000e+00
    vertex 0.000000e+00 2.000000e+00 0.000000e+00
  endloop
endfacet
facet normal -1.000000e+00 0.000000e+00 0.000000e+00
  outer loop
    vertex 0.000000e+00 2.000000e+00 1.000000e+00
    vertex 0.000000e+00 2.000000e+00 0.000000e+00
    vertex 0.000000e+00 0.000000e+00 0.000000e+00
  endloop
endfacet
facet normal 0.000000e+00 0.000000e+00 * -1.000000e+00
  outer loop
    vertex 2.000000e+00 2.000000e+00 0.000000e+00
    vertex 2.000000e+00 0.000000e+00 0.000000e+00
    vertex 0.000000e+00 2.000000e+00 0.000000e+00
  endloop
endfacet
...
```



MCA Session 1 Activity Discussion



3D Printer Hardware

- What type of info might be sent to the machine?
- What components in the schematic on the right can be removed and why?
- What's the difference between firmware and software?
- If you never saw the CAD file, but had the slice files, could you print the part?
- What type of info might be sent from the machine to the STL file in the software?





From Slices to Layers


- Slices and layers are not the same thing
- Slice is a 2D cross-section of the CAD (STL) model
- Layer is a 2.5D thin slab of material between two slices
- Slice exists at the top and bottom of a layer...
- Important question then becomes: which slice corresponding to a layer (top or bottom)
- The same slices can create different layers



Over and Under Approximation Error






Different Geometry, Similar Slice/Layer Problems




What is the “layer”

Layer Generation Techniques

- Most layers are 2.5 D objects (x-y contour and some constant depth)
- Creating each layer is significantly easier than creating 3D freeform shape
- Some systems can perform “Adaptive Slicing” to change the thickness of a layer
- Layers are zeroth order approximations of 3D models
- Some of the best systems can perform First-order ruled approximations of the shape



Zeroth-order



First-order

Layers vs. 3D Shapes

- Isometric views of the two shapes on the right highlight the importance of orienting a part for 3D printing
- Which part will be “near net shape”?
- (Hint: layer thickness is almost always larger than X-Y positional tolerance)




Fig. 10. Cuboid dixel-based simulation for vector-based MMLM process.

MCA Session 1, In-Class Activity #2

- Theme: Hands-On machine component investigation
- Use the provided explanation and hands-on investigation of machine components to answer these questions:

1. For a machine component that is heated and a second that moves, where/when in the G-code do the components get the info they need?

2. What type of data conversion occurs for the motor(s) used in the following G-code commands:

- `G1 X9.202 Y15.578 Z0.600 F9000`; Travel Move
- `G1 X8.962 Y15.888 Z0.600 F5400 A47.05344`; Inset

3. If you never saw the CAD file, but had the slice files, could you print the part?

